

Dresser Natural Gas Solutions 16240 Port Northwest Dr. Houston, Texas 77041, USA T +1 800 521 1114 F +1 800 335 5224


Product Update Notice RCS Actuators

MAR1600-65 / MAR 4000-160 Actuators 90 Degree Gear Box Replacement June 26, 2019

Product Update Notices provide information about updates, enhancements, improvements, certifications and other changes to new and current Dresser Industrial Products Group. The information in these notices is intended to help you take advantage of the continuous improvements to Dresser Industrial Products Group and services.

Product Update Overview

The 1600-65, and 4000-160, are interchangeable with old units, but shaft diameter has changed from 3.25" to 3.125". This will require a new, or modified coupling.



Product Update Notice Rev A (06/2016)

Product Update Details

92-15 Gearbox assembly 90 degree is replacing current gearbox for 1600-65 and 4000-160 actuators. As offered by current vendor. New actuator/gearbox assembly can replace old units, but it will require a new, or modified coupling. Shaft diameter has changed to 3.125"

User Benefits

RCS Product continuity on MAR1600/4000 Series. Reduced size and weight on gear box

Support Contacts

For further information, you may contact:

- Your Dresser NGS Sales Manager
- Phone 832-590-2306, or toll-free number 1-800-945-9898
- Via email at rcs.info@dresserngs.com.

Affected Parts List

• 90-893 Gearbox Assembly, 90 degree

